

COMUNICADO

Gobierno de Gibraltar: Ministerio de Turismo, Asuntos Comerciales, Transporte Público y Puerto

Norstar

Gibraltar, 18 de noviembre de 2013

El barco NORSTAR, que se encuentra amarrado en Detached Mole, ha sido contratado como nave de carga para el material dragado durante los trabajos en la cuenca de Ocean Village¹.

A última hora de la tarde del 17 de noviembre, tras haber cargado aproximadamente 4.000 toneladas de material, se produjo un desplazamiento de la carga que afectó a la estabilidad de la embarcación, haciendo que se escorase aproximadamente 18°. La tripulación de la nave, con la excepción del capitán y el ingeniero jefe, ha sido evacuada.

Los propietarios de la nave están gestionando el asesoramiento técnico para corregir la situación y se espera que los peritos puedan llevar a cabo una inspección a lo largo de la mañana de hoy.

Nota a redactores:

Esta es una traducción realizada por la Oficina de Información de Gibraltar. Algunas palabras no se encuentran en el documento original y se han añadido para mejorar el sentido de la traducción. El texto válido es el original en inglés que sigue.

Para cualquier ampliación de esta información, rogamos contacte con
Oficina de Información de Gibraltar
Miguel Vermehren, Madrid, miguel@infogibraltar.com, Tel 609 004 166
Sandra Balvín, Campo de Gibraltar, sandra@infogibraltar.com, Tel 661 547 573

¹ Un moderno complejo en sur de Gibraltar, que cuenta con puerto y zonas comerciales y residenciales;
<http://www.oceanvillage.gi/>



HM GOVERNMENT OF GIBRALTAR
Office of the Minister for Tourism, Commercial Affairs,
Public Transport and the Port
Suite 631, Europort
Gibraltar

PRESS RELEASE

No. 823/2013

Date: 18th November 2013

NORSTAR

The vessel NORSTAR, berthed at the Detached Mole, has been engaged to act as a holding barge for the dredged material arising from the dredge of Ocean Village basin.

During the late evening of the 17th November, having loaded some 4000 tonnes of dredged material, there was a shift of cargo affecting the stability of the vessel resulting in the vessel adopting a heel of around 18°. The crew of the vessel, apart from the master and chief engineer, have been evacuated.

The owners of the vessel are arranging technical advice to rectify the situation and surveyors are expected to attend this morning.

Telephone No: (350) 200 78871 (Centrex: 2750) ; Fax No: (350) 200 78899 (Centrex: 3511)
Email: info.mttp@gibraltar.gov.gi